

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 8 6 5 1 0 0 0 5	Manifest Document No.	2. Page 1 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Torrance, CA 90502				A. State Manifest Document Number 86234327		
4. Generator's Phone (553-6677)		6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7	8. US EPA ID Number	B. State Generator's ID 709745		
5. Transporter 1 Company Name J. C. Liquid Waste Disposal				C. State Transporter's ID 213-268-3137		
7. Transporter 2 Company Name				D. Transporter's Phone F. Transporter's Phone		
9. Designated Facility Name and Site Address Triple J 3650 E. 26th St. Vernon, CA		10. US EPA ID Number C I A T I O 8 0 0 3 6 8 1			G. State Facility's ID	
					H. Facility's Phone	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number) a. Hazardous Waste Liquid NOS ORM-E NA9189		12. Containers No. 001	Type TT	Total Quantity 05000	Unit Wt/Vol G	Waste No. 221
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above Bio-Degradable Coolant 10% Tramp Oil 2% Water 88%		K. Handling Codes for Wastes Listed Above C1				
15. Special Handling Instructions and Additional Information Guide #31 Use gloves, goggles, respirator - If load is rejected, return to DAC						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.						
Printed/Typed Name Donald C. Gerber		Signature <i>D. C. Gerber</i>	Month 02	Day 19	Year 1987	
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name SANTOS YBARRA WB 57361		Signature <i>Santos Ybarra</i>	Month 02	Day 19	Year 1987	
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature	Month	Day	Year	
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name Lambert Ding Tolosa Jr.		Signature <i>Lambert Ding Tolosa Jr.</i>	Month 02	Day 19	Year 1987	

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C A D 0 1 8 6 5 1 0 0 0 1 5	Manifest Document No.	2. Page 1 of 1	Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. 190th & Normandie Torrance, CA 90502				A. State Manifest Document Number 86234327		
4. Generator's Phone (553-6677)		6. US EPA ID Number C A D 0 5 8 0 1 8 3 6 7 1	8. US EPA ID Number	B. State Generator's ID 709745		
5. Transporter 1 Company Name J. C. Liquid Waste Disposal		10. US EPA ID Number C I A I T 0 1 8 0 0 1 3 6 8 1 1	12. Containers No. Type 001 TT 05000 G 221	C. State Transporter's ID 213-268-3137		
7. Transporter 2 Company Name				D. Transporter's Phone F. Transporter's Phone		
9. Designated Facility Name and Site Address Triple J 3650 E. 26th St. Vernon, CA				G. State Facility's ID H. Facility's Phone		
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				13. Total Quantity	14. Unit Wt/Vol	I. Waste No.
a.	Hazardous Waste Liquid NOS ORM-E	NA9189				
b.						
c.						
d.						
J. Additional Descriptions for Materials Listed Above B16-Degradable Coolant 10% Tramp Oil 2% Water 88%		K. Handling Codes for Wastes Listed Above				
15. Special Handling Instructions and Additional Information Use gloves, goggles, respirator - If load is rejected, return to DAC						
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations.						
Unless I am a small quantity generator who has been exempted by statute or regulation from the duty to make a waste minimization certification under Section 3002(b) of RCRA, I also certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and I have selected the method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment.						
Printed/Typed Name Donald C. Gerber		Signature sb	Month Day Year 10/21/987			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name SANTOS YBARRA WH 57361		Signature Santos Ybarra	Month Day Year 10/21/987			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name		Signature	Month Day Year			
19. Discrepancy Indication Space						
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name		Signature	Month Day Year			